

## Notice

**TSP Name:** Gulf South Pipeline Company, LLC

**TSP:** 78444247

**Category:** Critical

**Post Date/Time:** 06/09/2022 11:26:23AM

**Notice Type Desc:** Over-Under Performance

**Notice Effective Date/Time:** 06/09/2022 11:30:00AM

**Notice Stat Desc:** Supersede

**Notice End Date/Time:**

**Notice ID:** 5030417

**Response Date/Time:**

**Prior Notice:** 5030412

**Critical:** Y

**Reqrd Rsp Desc:** No response required

**Subject:** FLNG Unplanned Outage UPDATED

**Notice Text:** UPDATE: Based upon communications from FLNG, we anticipate zero gas flow until further notice. Accordingly, Gulf South will be reducing scheduled quantities to zero at all cycles at SLN 024329 - Stratton Ridge (to Freeport).

UPDATE: Based upon communications from FLNG, they anticipate zero gas flow for Gas Day June 9, 2022. Accordingly, Gulf South will be reducing scheduled quantities to zero at Evening Cycle at SLN 024329 - Stratton Ridge (to Freeport).

FLNG has experienced an unplanned disruption on Gas Day June 8, 2022. Current flowrate is zero dekatherms. Gulf South will be confirming SLN 024329 - Stratton Ridge (to Freeport) down to EPSQ at ID1 for Gas Day June 8, 2022. Future cycles will be evaluated one hour after the nomination deadline and will be subject to reductions due to underperformance.

Please contact your customer service representative with any questions.